

(96) COLUMNS - M1C1



(102) COLUMNS - M1C2



DETAIL "A" @ BEVEL

SHOP BILL

QTY.		DESCRIPTION	WT	IN	ADDN. MARK	SHIPPING MARK	REMARKS	WEIGHT
96		TS 5x5x'4	12	6 0		M1C1		18822.10
	96	'D' Rx11	0	11	pa			2882.15
	384	'D' 4x2	0	3	pb			163.33
	192	L 3 x 3 x '6	0	4	aa			459.51
		TOTAL WEIGHT						22327.09
102		TS 5x5x'4	11	9		M1C2		18720.57
	408	'D' 4 x 2	0	3	pb			173.54
	204	L 3 x 3 x '6	0	4	aa			488.23
		TOTAL WEIGHT						19382.34

APPROVAL AUTHORITY:
VERIFICATION OF DIMENSIONS, DETAILS, ETC. ARE REQUESTED WHERE INDICATED. IF EACH VERIFICATION IS NOT NOTED OTHERWISE, IT WILL BE ASSUMED TO BE CORRECT AS SHOWN.

SHOP NOTES :
ALL STUBS ARE FROM FACE OF CLIP ANGLES
ALL HOLE SPACING 3" C/C UNLESS NOTED
ALL BLOCK SIZES FROM FACE OF CLIP ANGLES
ALL REAR ENTRANT CUTS HAVE A MINIMUM OF '8" RADIUS CUTS.

VERIFY DIMENSION AND/OR DETAIL.

THIS PROJECT SHALL BE ERECTED PER THE AISC CODE OF STANDARD PRACTICE SPECIFICALLY PARAGRAPH 7.13 AS FOLLOWS:
7.13 CORRECTION OF ERRORS
NORMAL ERECTION OF OPERATIONS INCLUDE THE CORRECTION OF MINOR MISFITS BY MODERATE AMOUNTS OF REAMING, CHIPPING, WELDING OR CUTTING, AND THE DRAWING OF SLIGHTLY OUT-OF-LINE THROUGH THE USE OF DRIFT PINS. ERRORS WHICH CANNOT BE CORRECTED BY SUCH MEANS OR WHICH AFFECT THE STRENGTH OF MEMBERS OR CONNECTIONS, OR WHICH REQUIRE MAJOR CHANGES IN MEMBER CONFIGURATIONS ARE TO BE REPORTED TO THE ENGINEER OF RECORD BY THE ERECTOR. IT SHALL BE HIS DECISION IF, AND BY WHAT METHOD, CORRECTION SHALL BE MADE.
NO BACK CHARGES WILL BE ACCEPTED UNLESS APPROVED IN WRITING BY THIS OFFICE.

REVISIONS				
1	SRB	7-06	CHANGE COLS FOR FLR TO FLR ASSEMBLY	
	BY	DATE	DESCRIPTION	

NOTES:

E. Z. BREEZE
McMINNVILLE, TN.
(931) 635-3418

STRUCTURE: FOOTHILLS APARTMENTS
LOCATION: NORTH LITTLE ROCK, AR.
DETAIL: COLUMNS
CUSTOMER:
ENGR OR ARCH: SCHWALTZ ENGINEERING, INC.

PAINT: ONE STD SC PRIMER
CLEANING:

DRAWN	SRB	SHOP ORDER	SHEET NO.	REV.
DATE	6-14		M1	1
CHECKED	SGL			
DATE	6-23			

MATERIAL GRADE: A992 GR50
BOLTS: 'E⌀ U.N.T.D.